

US EPA ARCHIVE DOCUMENT

Situation Photo Log

Friday, October 12, 2012

Kalamazoo River / Enbridge Spill

Water / Sediment Temperatures

Location	Water Temp. (°F)	Sediment Temp. (°F)
C0.4 Boat Launch Gauge	54.05	53.64
Ceresco Dam Containment Boom	51.89	55.14
E4.0 Boat Launch Gauge	48.81	52.22
E0.5 Boat Launch Gauge	49.79	51.63

Prepared by:
Matthew Haak
START-USEPA
Situation Unit Leader



1. Morrow Lake north cove no sheen observed.



2. Morrow Lake south cove no sheen observed.



3. Morrow Lake Delta Gate E no sheen observed.



4. Morrow Lake Delta Gate C no sheen observed.



5. MP36.25 Island no sheen observed.



6. MP26.25 RDB no sheen observed.



7. MP26.0 RDB Sediment trap no sheen observed.



8. MP24.75 no sheen was observed.



9. MP23.1 RDB no sheen observed.



10. MP30.8 Sediment Trap no sheen observed.



11. MP21.5 Custer Drive bridge no sheen observed.



12. MP5.45 LDB spontaneous sheen and tar glob observed.



13. Ceresco Dam Control Point boom.



14. Sheen observed collecting along the Ceresco Dam control point boom.